

Splicing Connectors for Quick & Easy Connections

WAGO

Pull the lever up, insert a conductor and push the lever back down - done!



- Quickly and easily connect all types of conductors upto 4mm² and 6mm²
- Easy-to-use operating lever for tool-free terminations
- High current carrying capacity up to 32A & 41A
- Convenient testing via two test slots even after installation
- Perfect for distribution applications thanks to mounting carrier
- Conserve space in the junction box, due to it's compact size

